THERMOPLASTIC PAVEMENT

MARKINGS IN VERMONT

REPORT 95-2

APRIL 1995

STATE OF VERMONT AGENCY OF TRANSPORTATION MATERIAL AND RESEARCH DIVISION

PATRICK J. GARAHAN, SECRETARY OF TRANSPORTATION FRANK C. EVANS, DIRECTOR OF CONSTRUCTION AND MAINTENANCE ROBERT F. CAULEY, MATERIALS AND RESEARCH ENGINEER

Prepared By:

Craig Graham Transportation Technician III

Reviewed By:

Robert Cauly

Robert F. Cauley Materials and Research Engineer

Date: APR 7 1999

Thermoplastic Pavement Markings in Vermont

INTRODUCTION:

Over the next few years, solvent based traffic marking paint will be phased out and substitutes will have to be identified. Some of the proposed replacements include waterborne paint, epoxy, polyester, and thermoplastic pavement markings. In the State of Vermont, thermoplastic pavement markings have been used on all new construction projects since 1992. Due to winter snowplow operations, some problems have occurred with respect to product durability. For this reason, the Agency of Transportation's Materials and Research Division undertook a detailed study of pavement markings during the summer of 1994. The purpose of this study was to record the overall performance of all thermoplastic markings throughout the state. The major portion of this process entailed a detailed inspection of all 1992 and 1993 projects, as well monitoring most new applications. Skid resistance and retroreflectivity were also considered. A computer database was used to chronicle the information pertaining to this inspection.

INSPECTION OF 1992 AND 1993 PROJECTS:

Originally it was hoped that thermoplastic pavement markings would have a life of five years. During early 1994, a decision was made to survey year old and two year old thermoplastic markings throughout the state. The procedure for this inspection resulted in a quantitative analysis of both edge lines and lane lines expressed as a numeric rating and as a percent of loss. A descriptive rating was also assigned.

The inspections took place during May, early June, and September 1994. Seventy-six projects constructed in 1992 and 1993 were surveyed for durability during this time. The procedure entailed a detailed visual survey which was accomplished by driving over the entire project slowly and observing the lines. For the purposes of the inspection, each project was broken down into smaller segments. Each of these segments then received a rating for the left edge, center, and right edge line. The ratings were averaged and weighted by multiplying the average rating by the segment length in feet. All of the segments were totalled and divided by the length of the project in feet. This resulted in the overall rating, which determined the percentage of retained material and the descriptive rating that would be assigned to the project.

On the average these projects have performed satisfactorily over the previous one to two years. There were a few noticeable problems, as certain projects had significant losses associated with them. One such project on VT 11 in Chester and Springfield had a complete loss of edge lines for at least 0.5 miles. Other such situations did exist, but they were not necessarily as severe. The majority of the problems appeared to be due to bonding problems associated with a low application temperature, coupled with snowplow scraping. Of all projects inspected, 64% were rated at or above a good rating, and 19% were rated at or below a poor/fair rating. The following table breaks the percentages down by each category:

| RATING | NUMBER OF PROJECTS | 9 |
|----------------|--------------------|------|
| Poor | 11 | 15% |
| Poor/Fair | 3 | 48 |
| Fair | 10 | 13% |
| Fair/Good | 3 | 48 |
| Good | 19 | 25% |
| Good/Excellent | 8 | 118 |
| Excellent | 21 | 28% |
| Total | 76 | 100% |

Although a majority of the projects had good results with thermoplastic pavement markings, there is concern with the 19% (14 projects) rated at or below poor/fair. As with the problems associated with VT 11 in Chester and Springfield, the majority of these poor ratings can best be attributed to poor bonding due to low temperatures at application.

Presently there are two contractors that apply thermoplastic in the State of Vermont. A third contractor (from out of state) also was awarded a bid on a state project, but only applied epoxy markings and therefore is not considered here. The following table illustrates the breakdown of projects between the two in-state contractors:

| | Con | ntractor | <u>A</u> | | Con | tractor | B | |
|----------------|-------|----------|----------|------|-------|---------|-------|------|
| | 51 of | f 76 pro | jects | | 25 of | 76 pro | jects | |
| | | (67.1%) | | | | (32.9%) | | |
| Rating | 1992 | 1993 | Total | 8 | 1992 | 1993 | Total | 8 |
| Poor | 1 | 0 | 1 | 28 | 6 | 5 | 11 | 448 |
| Poor/Fair | 0 | 0 | 0 | - | 2 | 1 | 3 | 12% |
| Fair | 3 | 1 | 4 | 88 | 4 | 2 | 6 | 24% |
| Fair/Good | 2 | 1 | 3 | 6% | 0 | 0 | 0 | - |
| Good | 8 | 8 | 16 | 318 | 0 | 3 | 3 | 12% |
| Good/Excellent | t 3 | 4 | 7 | 148 | 0 | 1 | 1 | 48 |
| Excellent | 3 | 17 | 20 | 39% | 0 | 1 | 1 | 48 |
| Total | | | 51 | 100% | | | 25 | 100% |

Given the wide difference between the contractors, the most likely reason for the wide disparity of the ratings is the application technique chosen by each contractor. Contractor A has a large applicator truck which is geared more to long line application, while Contractor B has a much smaller vehicle. As a result, they can store less heated material and must stop the vehicle and let the material heat to application temperature once their tank is empty. This increases the chance that some material may be applied too cool. As was said previously, if there is a low temperature when applying this material, a bond failure may occur, which would facilitate the loss of material by snowplow scraping. It does appear that Contractor B improved the application techniques from 1992 to 1993; however, this may be due to the fact that the 1992 applications have been in place for two winters while the 1993 applications have only weathered one winter.

Another important factor is the performance of the two different types of thermoplastic. Currently we have a hydrocarbon and an alkyd thermoplastic material approved for use in the State of Vermont. The following table illustrates the differences in the durability of these two materials:

| 1 | Hydroc 45 o | arbon Th f 76 pro (59.2%) | ermopla jects | rmoplastic ects | | Alkyd Thermoplastic 31 of 76 projects (40.8%) | | |
|----------------|----------------|---------------------------------|------------------|--------------------|------|---|-------|------|
| Rating | 1992 | 1993 | Total | 8 | 1992 | 1993 | Total | 8 |
| Poor | 1 | 0 | 1 | 2% | 6 | 5 | 11 | 35% |
| Poor/Fair | 0 | 0 | 0 | - | 2 | 1 | 3 | 10% |
| Fair | 3 | 0 | 3 | 68 | 5 | 2 | 7 | 23% |
| Fair/Good | 0 | 0 | 0 | - | 2 | 1 | 3 | 10% |
| Good | 7 | 8 | 15 | 348 | 1 | 3 | 4 | 138 |
| Good/Excellent | t 2 | 4 | 6 | 138 | 1 | 1 | 2 | 6% |
| Excellent | 3 | 17 | 20 | 45% | 0 | 1 | 1 | 38 |
| Total | | | 45 | 100% | | | 31 | 100% |

Since the hydrocarbon is used only by Contractor A and the alkyd is used by both, it is interesting to note the differences between the two materials. Only one hydrocarbon was rated in either of the lower two categories, while 14 alkyds were present here. Alkyd does have a limited application temperature range (400 - 430 degrees F), which may account for the failures above.

Generally it can be said that projects where hydrocarbon has been applied using long line vehicles with automatic controls have a greater chance of realizing a five year life than those with alkyd material that has been applied with a much less sophisticated apparatus.

APPLICATION OF NEW THERMOPLASTIC MARKINGS:

Another task was to evaluate and observe new applications of pavement markings. A variety of tests were performed on each project, three of which include:

- Checking mil thickness of the pavement marking. This is done by placing duct tape on the projected line path, letting the thermoplastic truck mark over it, and then pulling up the tape to measure the mil thickness. Our specification assigns 125 mils as the standard.

- Checking for moisture on the pavement. The inspector places a small piece of tar paper down on the pavement and has the thermoplastic truck place some material on it. After a few seconds the tar paper is turned over and the underside is observed for droplets of moisture. If any moisture is present the material should not be installed.

- Checking the temperature of the thermoplastic. This is done by using a digital thermometer, and measuring the temperature of the flowing material(i.e., material between the truck and the pavement). The thermometer reading should be no lower than 400 degrees F and no higher than 440 degrees F.

Twenty five projects were inspected. These projects were evenly split between the two contractors, with 12 applied by Contractor A, and 13 by Contractor B. Another firm had a contract to apply thermoplastic, but, due to the method of application they chose, they were not allowed to apply it. As a result they had to subcontract to one of the in-state contractors. This firm did apply epoxy paint on one of the 1994 projects, and is being tracked separately.

Due to time and lack of resources, not all of the new projects were inspected. Again, overall, the conduct of the applications was satisfactory; however, there were problems associated with one contractor's equipment. This equipment utilized the ribbon extrusion method, which is not approved for use in this state. As a result, this equipment will not be able to be used in 1995 and beyond.

At this time, little can be determined from these applications. A number of projects did have in excess of 130 mils of thickness on their lines. After the end of the current snowplowing season, these projects will be resurveyed and any significant losses will be documented.

RETROREFLECTIVITY:

During the late summer of 1990, thermoplastic markings were placed on VT 67A in Bennington. These lines were manufactured by Pavemark Inc. of Atlanta GA, and were of the alkyd type, and were originally used as a comparison for 3M Series 380 and 350 Pavement Marking Tape (Report U94-11). Retroreflectivity readings have been taken over the past four years and are summarized in the following table. For our purposes 100 millicandellas (mcdl) or lower is considered poor.

| | MILLICAN | DELLAS | |
|---------|----------|--------|--|
| DATE | WHITE | YELLOW | |
| 9/6/90 | 460 | 342 | |
| 5/10/91 | 100 | 199 | |
| 8/9/94 | 144 | 121 | |

Although there is a three year gap between the second and third readings, these readings are still significant. This section of VT 67A can best be described as an urban collector, with an intersection between it and US 7 within 500 feet of these markings. This data shows that, even after three years, the lines still have good reflectivity. It is unknown why the reading for white thermoplastic on May 10, 1991 differs so much from the reading on August 9, 1994. One problem could have been that the line was not swept or cleaned off prior to testing. Although the results are promising, more readings will have to be gathered before any conclusions can be drawn.

SKID RESISTANCE:

Resistance to slippage of vehicles on the pavement markings is an important factor to consider. In order to measure this, the Materials and Research Division underwent a test in September, 1993 to quantify the skid resistance. The test was conducted at the Caledonia County State Airport, with thermoplastic pavement markings applied in four 100 foot test stripes. White traffic paint was applied on the tarmac in two 100 foot sections. For the thermoplastic tests, glass was added as follows: one section with 100% beads, one with no beads, one section with equal parts of glass beads and crushed glass, and one with 70% glass beads and 30% crushed glass. The pavement was dried with a Ripack heat shrinker for 50 feet of the 100 foot length for each of the thermoplastic sections except for the one with no beads.

Skid resistance was tested in 1993 and 1994, with both a portable British Pendulum Tester (BPT) and a FHWA portable trailer mounted skid tester. Each line was tested in five different locations with the BPT, and three separate skid runs with the FHWA equipment. Statistical analysis was used to compare the readings from the different test devices, This analysis showed that, the skid resistance of the thermoplastic with beads is the same as that of the paint with beads, as well as improving over one winter. This process was detailed in report U94-15. Unofficial testing was also conducted on various highways throughout Central Vermont in 1993, utilizing the BPT. Edge lines and adjacent pavement areas were tested on VT 14 in Williamstown, VT 66 in Randolph as well as the Berlin State Highway. These tests showed that even over one winter the skid resistance improved greatly compared with the adjacent pavement.

SUMMARY :

Overall thermoplastic pavement markings are performing satisfactorily in Vermont. Although data is limited, retroreflectivity and skid resistance appear to be acceptable. Hydrocarbon thermoplastic applied by fully automated long line vehicles has, on the average, outperformed alkyd material applied with less sophisticated smaller vehicles. Application techniques continue to be a problem, but with added experience the number of projects rated at or below a poor/fair rating should decrease. Again, as with all research projects, performance monitoring will continue with an emphasis on skid resistance, durability and retroreflectivity of the material. Further reports and updates will be published as required.

Run date: 03/10/95

Excellent Applications

| | Project | | Applied | Material |
|------|------------------|---------------------------|----------|----------|
| | STP 9333(1)S | Lemington | 09/01/92 | SG70 |
| | RS 0311(1) | Trov | 09/01/92 | SG70 |
| | STP 9269(1)S | Morristown | 07/01/92 | SG70 |
| | CMRS0113(55) | Windsor/Hartland | 09/01/93 | SG70 |
| | F 017-(19) | New Haven-Waltham | 09/08/93 | SG70 |
| | F017-1(19) | Ferrisburgh-Vergennes | 06/01/93 | SG70 |
| | F019-4(23) | Waltham-Ferrisburgh | 06/01/93 | SG70 |
| | IR089-2(17) | Waterbury-Richmond | 05/01/93 | SG70 |
| | STP 9303(1)S | Cambridge-Waterville | 05/26/93 | SG70 |
| | STP 9304(1)S | Readsboro-Searsburg | 05/01/93 | SG70 |
| | STP 9305(1)S | Cambridge | 07/01/93 | SG70 |
| | STP 9307 | Corinth-Topsham | 08/01/93 | SG70 |
| | STP 9315(1)S | Cambridge | 07/01/93 | SG70 |
| | STP 9319(1)S | Guilford-Brattleboro | 06/01/93 | SG70 |
| | STP 9330(1)S | Westmore-Brownington | 07/28/93 | SG70 |
| | STP 9340 | Shoreham | 05/01/93 | SG70 |
| | STP 9348(1)S | Newfane-Townsend | 09/21/93 | SG70 |
| | STP 9353(1)S | Dover-Stratton | 06/01/93 | SG70 |
| | STP 9354(1)S | Peru-Landgrove | 06/01/93 | SG70 |
| | STP-9317 | Whitingham | 06/01/93 | SG70 |
| | STP 9344(1)S | Newbury | 05/01/93 | Pavemark |
| Good | to Excellent App | lications | | |
| | Project | | Applied | Material |
| | STP 9222(1)S | Randolph | 09/25/92 | SG70 |
| | STP 9248(1)S | Derby-Charleston | 06/01/92 | SG70 |
| | STP 9260(1)S | Brighton-Morgn-Warrn Gore | 10/01/92 | Pavemark |
| | CMRS 0113(54) | Sutton | 06/01/93 | SG70 |
| | STP 9274(1)S | St. Albans | 09/01/93 | SG70 |
| | STP 9326(1)S | Bethel-Randolph | 07/01/93 | SG70 |
| | STP 9339(1)S | St. Albans-Sheldon | 08/01/93 | SG70 |
| | STP 9314(1)S | Warren Gore-Norton | 06/01/93 | Pavemark |
| Good | Applications | | | |
| | Project | | Applied | Material |
| | F019-3(43) | Rutland City | 07/01/92 | Pavemark |
| | F026-1(37) | Ryegate-Newbury | 06/01/92 | SG70 |
| | RS 0113(5) | Dummerston | 05/01/92 | SG70 |
| | STP 9250(1)S | Dummerston | 05/05/92 | SG70 |
| | STP 9270(1)S | Brighton-Ferdinand | 09/01/92 | SG70 |

Page: 1

Good Applications (ctd)

| Project | | Applied | Material |
|--------------|---------------------|----------|----------|
| STP 9328(1)S | Hartland | 10/01/92 | SG70 |
| STP 9349(1)S | Weathersfield | 09/29/92 | SG70 |
| STP 9355(1)S | Bristol-St.George | 08/01/92 | SG70 |
| F010-1(32) | Woodford-Searsburg | 06/01/93 | SG70 |
| RS 0113(53) | Lyndon | 09/01/93 | SG70 |
| STP 9251(1)S | Newbury-Ryegate | 09/01/93 | SG70 |
| STP 9259(1)S | Lyndon | 05/01/93 | SG70 |
| STP 9262(1)S | Castleton | 12/07/93 | SG70 |
| STP 9266(1)S | East Haven-Newark | 06/01/93 | SG70 |
| STP 9334(1)S | Orwell-Shoreham | 06/01/93 | SG70 |
| STP 9350(1)S | Ludlow- Bridgewater | 06/21/93 | SG70 |
| STP 9318(1)S | Johnson | 08/01/93 | Pavemark |
| STP 9267(1)S | Cambridge-Fairfax | 06/01/93 | Pavemark |
| STP 9347(1)S | Stowe | 08/01/93 | Pavemark |

Fair to Good Applications

| Project | | Applied | Material |
|--------------|------------|----------|----------|
| | | | |
| STP 9225(1)S | Colchester | 07/10/92 | Pavemark |
| RS 0177(4) | Strafford | 06/01/92 | Pavemark |
| F019-3(46)S | Rutland | 07/01/93 | Pavemark |

Fair Applications

| Project | | Applied | Material |
|---------------|------------------------|----------|----------|
| F034-2(10)c/1 | Troy-Newport | 09/01/92 | SG70 |
| HES 5500(6)S | Williston | 09/01/92 | SG70 |
| IR091-1(22) | Hartland-Hartford | 06/01/92 | SG70 |
| STP 9325 | Williamstown | 07/01/93 | Pavemark |
| STP 9336(1)S | Berkshire | 07/01/92 | Pavemark |
| STP 9342(1)S | Ripton | 09/01/92 | Pavemark |
| STP 9351(1)S | Richmond | 09/01/92 | Pavemark |
| STP 9272(1)S | Richford | 07/01/92 | Pavemark |
| STP 9301(1)S | Waterford-St.Johnsbury | 05/01/93 | Pavemark |
| STP 9360(1)S | Waterbury | 07/01/93 | Pavemark |
| | | | |

Poor to Fair Applications

| Project | | Applied | Material |
|--------------|----------|----------|----------|
| | | | |
| STP 9311(1)S | Chelsea | 08/01/92 | Pavemark |
| STP 9332(1)S | Franklin | 07/01/92 | Pavemark |
| STP 9343 | Bradford | 06/01/93 | Pavemark |

Poor Applications

| Project | | Applied | Material |
|----------------|----------------------------|----------|----------|
| F026-2(4)S | Newbury | 06/01/92 | SG70 |
| F134-3(17) C/2 | Derby-Newport | 10/01/92 | Pavemark |
| STP 9241(1)S | Sheldon-Franklin | 07/01/92 | Pavemark |
| STP 9268(1)S | East Middlebury | 09/01/92 | Pavemark |
| STP 9313(1)S | Thetford | 08/01/92 | Pavemark |
| STP 9306 | Thetford | 08/01/92 | Pavemark |
| STP 9335(1)S | Richford | 07/01/92 | Pavemark |
| STP 9320(1)S | Royalton-Bethel-Randolph | 06/01/93 | Pavemark |
| BRZ 1441(16) | Arlington | 05/01/93 | Pavemark |
| RS0134(8) | Chester/Springfield(5 Con) | 09/01/93 | Pavemark |
| STP 9254(1)S | Moretown | 08/01/93 | Pavemark |
| STP 9310(1)S | Burke | 05/01/93 | Pavemark |