




BARRIER FENCE (LINE STYLE)
653.50



BRUSH LAYER
653.75, DETAIL




CHECK DAM (LINE STYLE)
653.25, DETAIL




COFFERDAM (LINE STYLE)
208.40




CURB DROP INLET PROTECTION
653.40, DETAIL




DUST CONTROL
609.10 & 15



PIPE INLET PROTECTION
653.40, DETAIL




EXCAVATED DROP INLET PROTECTION
653.40, DETAIL




FIBER ROLL (EROSION LOG)
653.60, DETAIL




FILTER BAG
653.45, DETAIL




FILTER FABRIC DROP INLET PROTECTION
653.40, DETAIL




LIVE CUTTINGS/LIVE STAKES PLANTING
653.70, DETAIL




LIVE FASCINE
653.65, DETAIL




PROJECT DEMARCATION FENCE (LINE STYLE)
653.55




ROLLED EROSION CONTROL PRODUCT (RECP)
653.20 (TEMP. EROSION MATTING)




SEDIMENT BASIN
INCIDENTAL TO COFFERDAM 208.40




SILT FENCE(LINE STYLE)
649.5I, DETAIL




SILT FENCE WOVEN WIRE(LINE STYLE)
649.5I5, DETAIL




STABILIZED CONSTRUCTION ENTRANCE
653.35, DETAIL, VEHICLE TRACKING PAD



STONE & BLOCK DROP INLET PROTECTION
653.40, DETAIL



SURFACE ROUGHENING
INCIDENTAL TO CONTRACT



TURBIDITY CURTAIN
649.6I, DETAIL, FILTER CURTAIN

